

Link do produktu: <https://sklep.pomtyczyn.pl/uszczelniacz-walu-korbowego-tylny-claas-renault-deutz-fendt-115x140x16-mm-01160097-02234134-p-655.html>



Uszczelniacz wału korbowego tylny Claas Renault Deutz Fendt 115x140x16 mm / 01160097, 02234134

Cena	89,00 zł
Dostępność	Niedostępny
Numer katalogowy	02234134
Kod producenta	02234134

Opis produktu

Uszczelniacz wału korbowego tylny Claas Renault Deutz Fendt 115x140x16mm 01160097 02234134

Informacje techniczne:

Średnica wewnętrzna: 115mm

Średnica zewnętrzna: 140mm

Grubość: 16mm

Zastosowanie:

ciągniki Claas / Renault 50-12LB, 50-12V, 55-12F, 55-12LB, 55-12V, 55-14LB, 55-14V, 70-12F, 70-12LB, 70-12V, 70-14F, 70-14LB, 70-14V, 80-12F, 80-12V, 80-14F, 80-14V, Basso 130, Basso 140, Dionis 110, Dionis 120, Dionis 130, Dionis 140, Fructus 110, Fructus 120, Fructus 130, Fructus 140, Pales 210, Pales 230, Pales 240

ciągniki David Brown 1690, 1690T, 1594, 1694

ciągniki Deutz 10006, 13006, 4006, 4006F/S, 4006U, 4506, 4506F, 5006, 5006F, 5006U, 5206, 5206F, 5206U, 5506, 5506F, 5506U, 6006, 6006F, 6006U, 6206, 6206F, 6206U, 6806, 6806F, 6806U, 7006, 7006F, 7006U, 7206, 7206A, 7206F, 7206U, 7506, 7506F, 7506U, 8006, 9006, 9006A, 9006F, 9006U, 4007, 4007F, 4007U, 4507, 4507A, 4507F, 4807, 4807A, 4807F, 5207, 5207A, 5207F, 6007, 6007A, 6007F, 6207, 6207A, 6207F, 6507, 6507A, 6507F, 6807, 6807A, 6907, 7007, 7007A, 7207, 7207A, 7807, 7807A, Agrocompact 3.30V/F, Agrocompact 3.50S, Agrocompact 3.50V/F, Agrocompact 3.70V/F, Agrocompact 3.90F, Agrocompact 3.90S, Agrolux 60, Agrolux 70, Agrolux 80, Agrolux 90, Agroplus 60, Agroplus 70, Agroplus 80, Agroprima 4.31, Agroprima 4.36, Agroprima 4.46, Agroprima 4.51, Agroprima 4.56, Agroprima 6.06, Agroprima 6.16, Agrostar 4.61, Agrostar 4.71, Agrostar 6.11, Agrostar 6.21, Agrostar 6.31, Agrostar 6.61, Agrostar 4.68, Agrostar 4.78, Agrostar 6.08, Agrostar 6.28, Agrosun 100, Agrosun 120, Agrosun 140, Agroextra 3.57, Agroextra 4.07, Agroextra 4.17, Agroextra 4.47, Agroextra 6.07, Agroextra 6.17, 4507C, 4807C, 5207C, 6007C, 6207C, 6507C, 6807C, 6907C, 7007C, 7207C, 7807C, D 55, DX140, DX160, DX160A, DX250, DX250A, DX250V, DX3500, DX3700, DX3900, DX50, DX55, DX80, DX80A, DX3.10SC, DX3.30SC, DX3.50SC, DX3.60SC, DX3.65SC, DX3.70SC, DX3.80SC, DX3.90SC, DX3.10V, DX3.30V/F, DX3.50S, DX3.50V/F, DX3.70V/F, DX3.90F, DX3.90S, DX3.10VC, DX3.30VC, DX3.50VC, DX3.60VC, DX3.65VC, DX3.70VC, DX3.75VC, DX3.90VC, DX4.10, DX4.11, DX4.30, DX4.31, DX4.51, DX6.05, DX6.06, DX6.10, DX6.30, DX6.50, DX7.10, Dxab 110, Dxab 120, Dxab 145, Dxab 160, Dxab 80, Dxab 86, Dxab 90, Dxab 92, Dxbis 110, Dxbis 120, Dxbis 140, Dxbis 145, Dxbis 160, Dxbis 85, Dxbis 90, Hopfen DX4.17, Hopfen DX4.57, Intrac 2002, Intrac 2003, Intrac 2004, Intrac 2005, Intrac 2006, Intrac 6.30, Intrac 6.30T, Intrac 6.60

Fendt Agrobil S821, Farmer 200S, Farmer 200SA, Farmer 200V, Farmer 200VA, Farmer 201S, Farmer 201SA, Farmer 203P, Farmer 203P/II, Farmer 203PA, Farmer 203PA/II, Farmer 203V, Farmer 203V/II, Farmer 203VA, Farmer 203VA/II, Farmer 204P, Farmer 204PA, Farmer 204V, Farmer 204VA, Farmer 205P, Farmer 205PA, Farmer 240S, Farmer 250K, Farmer 250KA, Farmer 250LE, Farmer 250S, Farmer 250SA, Farmer 250V, Farmer 250VA, Farmer 260P, Farmer 260PA, Farmer 260S, Farmer 260SA, Farmer 260V, Farmer 260VA, Farmer 270P, Farmer 270PA, Farmer 270V, Farmer 270VA, Farmer 275SA, Farmer 275V, Farmer 275VA, Farmer 280P, Farmer 280PA, F255GT Kommunal, F275GT Kommunal, F275GTAll Kommunal, F275GTII Kommunal, FL345, FL360, FL365, FL380, FLA380, F255GT, F275GT, F275GTII, F345GT, F345GTM, F360GTF, F360GTH, F370GT, F370GTA, F380GHA, F380GT, F380GTA, F380GTH, F390GTA, F395GHA, F395GTA

silniki Deutz F 5L 912, F 4L 912 H, BF 4L 913, BF 6L 912, BF 6L 913, BF 6L 913T, F 3L 912, F 3L 912 H, F 3L 913, F 3L 913 H, F

4L 913, F 4L 913 H, F 4L 912, F 6L 912, F 6L 913
silniki David Brown AD6/55T, AD6/55

Numery porównawcze: 01014589, 01160097, 0223 413, 02234134, 04150783, 04152349, 0423 7267, 04230193, 04230392, 04232267, 0634310200, 1014589, 1160097, 20020387, 20306765, 223413, 2234134, 4150783, 4152349, 4230193, 4230392, 4232267, 4237267, 6005000566, 6005026218, 634310200, 900.03.07.4377, 90003074377, A5584216, A6984038, B513934, D1160097, D2232134, D2234134, D4150783, D4230193, D4230392, D4232267, F100004150783, F148.200.210.030, F148200210030, HCD4230392, K262708, K306765, K4150783, S57544, S69980, SA380001, SA380002, VD04230392, VD04232267, VPC5016